FUEL FILL SLOW, OR DIFFICULT TO FILL— **VEHICLES BUILT BEFORE 4/26/2005**

TSB 05-15-12

FORD:

2005 Mustang

This article supersedes TSB 05-4-8 to update the vehicle build date information.

ISSUE

Some 2005 Mustang vehicles built before 4/26/2005, may exhibit the fuel tank being slow or difficult to fill. The condition may be described as, repeated rapid shut-offs of the filling station pump nozzle, or multiple nozzle shut-offs when attempting to fill the fuel tank. The condition may be due to the fuel tank vapor venting system inside the fuel tank.

ACTION

Install a new fuel tank. Refer to Section 310-01 of the Workshop Manual. The new fuel tank has a revised internal venting system to improve fuel filling.

NOTE

SOME PUMP NOZZLE SHUT-OFFS MAY BE DUE TO THE FILLING STATION PUMP DELIVERING THE FUEL TOO QUICKLY. THIS IS NORMAL.

PART NUMBER	PART NAME
5R3Z-9002-AA	Fuel Tank

WARRANTY STATUS: Eligible Under Provisions Of

New Vehicle Limited Warranty Coverage

OPERATION DESCRIPTION

TIME

051512A

2005 Mustang 4.0L SOHC: 1.8 Hrs.

Replace Fuel Tank (Includes Time To Drain, Refill And Transfer Any Necessary Parts) (Do Not Use With 9002A, 9275A, 9350E)

051512B

2005 Mustang 4.0L SOHC 2.2 Hrs.

Convertible: Replace Fuel Tank (Includes Time To Drain, Refill And Transfer Any Necessary Parts) (Do

Not Use With 9002A.

9275A, 9350E)

2005 Mustang 4.6L 3V: 051512C

2.0 Hrs.

2.4 Hrs.

Replace Fuel Tank (Includes Time To Drain, Refill And Transfer Any Necessary Parts) (Do Not Use With 9002A, 9275A,

9350E)

051512D 2005 Mustang 4.6L 3V

> Convertible: Replace Fuel Tank (Includes Time To Drain, Refill And Transfer Any Necessary Parts) (Do Not Use With 9002A,

9275A, 9350E)

DEALER CODING

BASIC PART NO. 9002

CONDITION CODE 42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safety. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.