TSB 07-1-7

FORD:

1996-1997 Thunderbird

1996-2007 Crown Victoria, Mustang, Taurus

1998-2003 Escort 2000-2007 Focus

2002-2005 Thunderbird 2005-2006 Ford GT

2005-2007 Five Hundred, Freestyle

2006-2007 Fusion 1996-1997 Aerostar

1996-2007 E-Series, Explorer, Ranger 1997-2004 F-53 Motorhome Chassis

1997-2007 Expedition, F-150, F-Super Duty

1998-2003 Windstar 2000-2005 Excursion

2001-2003 Explorer Sport

2001-2005 Explorer Sport Trac

2001-2007 Escape 2004-2007 Freestar

2005-2007 Escape Hybrid

1996-1997 Cargo 1996-1998 L-Series 1996-1999 F- B-Series 2000-2007 F-650, F-750

2006-2007 Low Cab Forward

LINCOLN:

1996-1998 Mark VIII 1996-1999 Continental 1996-2007 Town Car 2000-2006 Lincoln LS

2006 Zephyr 2007 MKZ

1998-2007 Navigator 2002-2003 Blackwood 2003-2005 Aviator 2006-2007 Mark LT

2007 MKX

MERCURY:

1996-1997 Cougar 1996-2005 Sable

1996-2007 Grand Marquis

1999-2002 Cougar 2003-2004 Marauder 2005-2007 Montego 2006-2007 Milan

1997-2007 Mountaineer 1998-2002 Villager 2004-2007 Monterey

2005-2007 Mariner Hybrid, Mariner

ISSUE

MERCON® Automatic Transmission Fluid is being replaced by MERCON® V as a service fluid for power steering systems originally requiring MERCON®.

ACTION

Beginning immediately all power steering applications requiring MERCON® can now be serviced using MERCON® V or MERCON® Automatic Transmission Fluid or dual usage fluids labeled MERCON® / MERCON® V. After July 1, 2007, MERCON® Automatic Transmission Fluid will no longer be manufactured, therefore, availability of this fluid will continue until remaining inventory has been depleted.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 07-1-7 (Continued)

SERVICE PROCEDURE

Service power steering systems requiring MERCON® with MERCON® V or MERCON® Automatic Transmission Fluid or dual usage fluids labeled MERCON® / MERCON® V.

CAUTION

APPLICATIONS RECOMMENDING TYPE F
AUTOMATIC TRANSMISSION AND POWER
STEERING FLUID MUST CONTINUE TO USE
THAT PARTICULAR FLUID. USE OF ANY OTHER
FLUID MAY CAUSE REDUCED FUNCTIONALITY
OR DAMAGE

PART NUMBER	PART NAME
XT-2-QDX XT-2-DDX XT-5-QM XT-5-DM	MERCON® (Quart) MERCON® (55 Gal. Drum) MERCON® V (Quart) MERCON® V (55 Gal. Drum)

WARRANTY STATUS: Information Only